



# Current Model List

730 Martin Luther King Jr Blvd Suite 300 Campus Box 3430 Chapel Hill, NC 27599-3430 | [www.hsrb.unc.edu](http://www.hsrb.unc.edu)

## HIGHWAY SAFETY RESEARCH CENTER CURRENT CAR SEAT RECALL LIST

Last Revision: April 11, 2025

Download this list & sign up for email notification of updates: [buckleupnc.org/car-seat-recall-list](http://buckleupnc.org/car-seat-recall-list)

### About Car Seats and Recalls

It is important for people to register their car seat with the manufacturer so that they are notified of recalls. Recalls can be issued for any failure to meet Federal Motor Vehicle Safety Standard (FMVSS) 213 including crashworthiness and deviations from the standards related to labeling, flammability, or for parts that may come loose and pose a choking hazard. All recalls should be corrected.

Car seats are required to have a label indicating the manufacturer, model information, and date of manufacture. If the label is missing on a car seat, contact the manufacturer to see if it can be identified through other information. A car seat should not be used if its recall status cannot be determined.

To report any suspected car seat defects, call the National Highway Traffic Safety Administration Auto Safety Hotline at 888-327-4236 / (TTY): 800-424-9153.

### About the HSRC Recall List

UNC Highway Safety Research Center compiles and updates this list based on information provided by the National Highway Traffic Safety Administration and the car seat manufacturers at the time the recall is announced. While every effort is made to keep this list up to date, sometimes new information is added or clarified after a recall is announced. Always confirm recall information with the car seat manufacturer. It is the manufacturer who can and should make the final determination if a specific car seat is subject to recall. Caregivers should contact the manufacturer's customer service with any questions.

### About Older Car Seats and Recalls

UNC HSRC also maintains an archived list of recalled car seats that are 10 or more years old. This list can be provided upon request. While these seats are likely expired in addition to being recalled, this list is provided for those circumstances where caregivers are using an expired seat and Technicians need to be able to check its recall status.

### Instructions for Using the HSRC Recall List

Find the manufacturer, model name, model number, and date of manufacture on the label of the car seat. Using this information, look to see if the seat's information matches any listings on the recall list. The list is alphabetized by manufacturer and model name. When in doubt, contact the manufacturer for clarification.

### For further information, contact:

Bevan Kirley or Kristel Robison  
UNC Highway Safety Research Center  
[cps@hsrb.unc.edu](mailto:cps@hsrb.unc.edu)

Sign up for Recall List Updates



**About the HSRC Recall List**

The UNC Highway Safety Research Center compiles and updates this list based on information provided by the National Highway Traffic Safety Administration and the car seat manufacturers at the time the recall is announced. While every effort is made to keep this list up to date, sometimes new information is added or clarified after a recall is announced. Always confirm recall information with the car seat manufacturer. It is the manufacturer who can and should make the final determination if a specific car seat is subject to recall. Caregivers should contact the manufacturer's customer service with any questions.

**Instructions for Using the HSRC Recall List**

Find the manufacturer, model name, model number, and date of manufacture on the label of the car seat. Using this information, look to see if the seat's information matches any listings on the recall list. The list is alphabetized by manufacturer and model name. When in doubt, contact the manufacturer for clarification.

**Refer to Page 8 for the Index of Recalls and Safety Notifications**

**Download this list & sign up for email notification of updates: [buckleupnc.org/car-seat-recall-list](http://buckleupnc.org/car-seat-recall-list)**

| <b>List No.</b>                            | <b>Model Name</b>                           | <b>Model No. (X or # = more numbers or letters follow)</b> | <b>Mfg Date</b>     | <b>Problem Type and Consumer Action</b>                                                                                                                                                                                                                                                                                                                                                                                      |
|--------------------------------------------|---------------------------------------------|------------------------------------------------------------|---------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>4moms</b>                               |                                             |                                                            |                     |                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 1)                                         | Infant Car Seat                             | 1032                                                       | 07/01/16-10/31/16   | The hooks that lock the carrier into the base can stick and fail to attach the carrier to the car seat base. Contact mfg. for free replacement seat.                                                                                                                                                                                                                                                                         |
| <b>Angel Guard (Merritt Manufacturing)</b> |                                             |                                                            |                     |                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 2)                                         | AngelRide Car Bed                           | All Models                                                 | 08/08/19-10/24/19   | The internal harness may not have been properly sewn where the buckle is attached. Contact mfg. for free replacement harness.                                                                                                                                                                                                                                                                                                |
| <b>babidéal (Dorel China America)</b>      |                                             |                                                            |                     |                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 3)                                         | Storm Booster                               | BC901BPXL                                                  | 02/28/19            | The label attached to the fabric cover may not have the required safety warnings and instructions. Affected models do not comply with FMVSS 213 labeling requirements. Contact mfg. for free replacement fabric cover.                                                                                                                                                                                                       |
| <b>Baby Jogger</b>                         |                                             |                                                            |                     |                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 4)                                         | City GO Infant Car Seat                     | BJ64510, BJ64529                                           | 11/03/14-04/30/15   | The labels, instruction manual, and registration card of affected models do not comply with FMVSS 213 requirements for content and formatting. Contact mfg. for free replacement car seat.                                                                                                                                                                                                                                   |
| <b>Baby Trend</b>                          |                                             |                                                            |                     |                                                                                                                                                                                                                                                                                                                                                                                                                              |
| 5)                                         | Hybrid 3-in-1 LX                            | FB48417, FB58181                                           | 07/14/16 - 07/23/16 | The center adjuster may detach in a crash when used in the harnessed mode with a child weighing more than 40lbs. Contact mfg. for free replacement seat.                                                                                                                                                                                                                                                                     |
| 6)                                         | Hybrid 3-in-1 Combination Booster Car Seats | FB49E14A                                                   | 12/06/21            | The LATCH webbing that secures the child restraint system to the lower anchorages may fray, which can reduce the strength of the webbing and fail to properly restrain a child in a crash. Contact manufacturer for replacement LATCH assembly webbing and installation instructions. Owners can continue to safely use the car seat by installing with the vehicle seat belt as outlined in the product instruction manual. |

| <b>List No.</b>   | <b>Model Name</b>                                    | <b>Model No. (X or # = more numbers or letters follow)</b>                                                                                                                                                                                                           | <b>Mfg Date</b>                                                                                                                                                        | <b>Problem Type and Consumer Action</b>                                                                                                                                                                                                                                                                                                                                                                                                                                                          |
|-------------------|------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Britax</b>     |                                                      |                                                                                                                                                                                                                                                                      | <b>888-427-4829 / 704-409-1699 - <a href="mailto:Britax.Recall@britax.com">Britax.Recall@britax.com</a> / <a href="http://www.britaxusa.com">www.britaxusa.com</a></b> |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
| 7)                | B-Safe 35<br>B-Safe 35<br>Travel Systems             | E1A183F, E1A185x,<br>E1A186R, E1A203F,<br>E1A205x, E1A206x,<br>E1A207E, E9LU65V,<br>E9LU66x, E9LU67x,<br>EXA185M, S02063xxx,<br>S03803xxx, S04144xxx,<br>S04145000, S04402800,<br>S04884xxx, S04975600,<br>S04978900, S05260200,<br>S06020xxx, S06147100,<br>S921800 | 11/01/15-<br>05/31/17                                                                                                                                                  | The center tab on the chest clips of the affected seats can break, presenting a choking hazard. Contact mfg. for repair kit. Affected seats can be safely used as long as consumers remove the chest clip or monitor it for signs of breakage.                                                                                                                                                                                                                                                   |
| 8)                | B-Safe 35 Elite<br>B-Safe 35 Elite<br>Travel Systems | E1A215x, E1A216P,<br>E1A221Q, E1A225x,<br>E1A226L, E9LS5xx,<br>EXA216L, S01298600,<br>S02063xxx, S02064000,<br>S04281xxx, S04628500,<br>S06018800, S06020xxx,<br>S06051300, S923700                                                                                  | 11/01/15-<br>05/31/17                                                                                                                                                  | The center tab on the chest clips of the affected seats can break, presenting a choking hazard. Contact mfg. for repair kit. Affected seats can be safely used as long as consumers remove the chest clip or monitor it for signs of breakage.                                                                                                                                                                                                                                                   |
| 9)                | B-Safe BOB 35                                        | E9LT34x, E9LT35X,<br>EXLT34A                                                                                                                                                                                                                                         | 11/01/15-<br>05/31/17                                                                                                                                                  | The center tab on the chest clips of the affected seats can break, presenting a choking hazard. Contact mfg. for repair kit. Affected seats can be safely used as long as consumers remove the chest clip or monitor it for signs of breakage.                                                                                                                                                                                                                                                   |
| 10)               | Companion                                            | E9L14, E9L20, E9L80                                                                                                                                                                                                                                                  | All                                                                                                                                                                    | Consumer Advisory - NOT A RECALL: Britax advises that the user should adjust the carrier handle so that it is completely down and behind the carrier after installation in the vehicle with or without the base assembly. Contact mfg. for additional info.                                                                                                                                                                                                                                      |
| 11)               | One4Life Slim<br>ClickTight                          | E1D197A, E1D197B,<br>E1D197F, E1D197G                                                                                                                                                                                                                                | 7/10/24-<br>7/12/24                                                                                                                                                    | Labels and user guide state an incorrect weight limit for rear-facing installation using the lower anchors. The maximum child weight for rear-facing installation with the lower anchors should be 35lbs. Contact manufacturer for replacement labels and instructions.                                                                                                                                                                                                                          |
| <b>Chicco USA</b> |                                                      |                                                                                                                                                                                                                                                                      | <b>877-424-4226 - <a href="http://www.chiccousa.com">www.chiccousa.com</a></b>                                                                                         |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
| >> 12)            | MyFit Zip Air                                        | 07079561970070,<br>04079561190070                                                                                                                                                                                                                                    | 09/01/20–<br>08/31/24                                                                                                                                                  | The car seat may allow excessive chest movement in a crash when used in the harnessed mode and installed using the following configuration: lap belt only, no tether, and recline position 3 or 4 (most upright). The car seat can continue to be used when installed using a different method, in accordance with the manufacturer's instructions. Note: manufacturer instructions indicate use of a tether is required when used in harnessed mode. Contact manufacturer for more information. |
| <b>Clek</b>       |                                                      |                                                                                                                                                                                                                                                                      | <b>866-656-2462 - <a href="http://www.clekinc.com">www.clekinc.com</a></b>                                                                                             |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
| 13)               | Flo                                                  | FL15, FL16, FL17, FL18,<br>FL19                                                                                                                                                                                                                                      | 07/05/14-<br>05/20/21                                                                                                                                                  | It is possible for a child to access and remove small pieces of foam from the seat cushion. Loose pieces of foam can be a choking hazard. Contact manufacturer for a remedy kit.                                                                                                                                                                                                                                                                                                                 |
| 14)               | Foonf                                                | F012, F014, F015, F016,<br>F017, F018, F019                                                                                                                                                                                                                          | 12/03/12-<br>05/20/21                                                                                                                                                  | It is possible for a child to access and remove small pieces of foam from the seat cushion. Loose pieces of foam can be a choking hazard. Contact manufacturer for a remedy kit.                                                                                                                                                                                                                                                                                                                 |
| 15)               | Liing                                                | LG19U1                                                                                                                                                                                                                                                               | 03/27/19-<br>09/14/20                                                                                                                                                  | A portion of the canopy can break if forcefully bent and leave behind a small plastic piece which could be a choking hazard. Contact manufacturer for a remedy kit.                                                                                                                                                                                                                                                                                                                              |

| <b>List No.</b>                              | <b>Model Name</b>                 | <b>Model No. (X or # = more numbers or letters follow)</b>                           | <b>Mfg Date</b>                                                                                 | <b>Problem Type and Consumer Action</b>                                                                                                                                                                                                                                                       |
|----------------------------------------------|-----------------------------------|--------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Clek (continued)</b>                      |                                   |                                                                                      |                                                                                                 |                                                                                                                                                                                                                                                                                               |
| 16)                                          | Liing                             | LG19U1                                                                               | 03/27/19-02/22/21                                                                               | The warning label affixed to some fabric covers may start to peel, potentially causing a choking hazard. Contact manufacturer for a remedy kit.                                                                                                                                               |
| 17)                                          | Liingo                            | LGO20U1                                                                              | 05/20/20-04/14/20                                                                               | A portion of the canopy can break if forcefully bent and leave behind a small plastic piece which could be a choking hazard. Contact manufacturer for a remedy kit.                                                                                                                           |
| 18)                                          | Liingo                            | LGO20U1                                                                              | 05/20/20-02/22/21                                                                               | The warning label affixed to some fabric covers may start to peel, potentially causing a choking hazard. Contact manufacturer for a remedy kit.                                                                                                                                               |
| 19)                                          | Olli                              | NA                                                                                   | 01/20/20-05/10/22                                                                               | Seat does not include a model number on label. All seats manufactured within the date range are included. A required label showing the proper way to install the booster seat with a lap/shoulder belt is missing. Contact manufacturer for a replacement label (clekinc.com/olliozzilabel).  |
| 20)                                          | Ozzi                              | NA                                                                                   | 03/01/20-05/10/22                                                                               | Seat does not include a model number on label. All seats manufactured within the date range are included. A required label showing the proper way to install the booster seat with a lap/shoulder belt is missing. Contact manufacturer for a replacement label (clekinc.com/olliozzilabel).  |
| <b>Combi USA</b>                             |                                   |                                                                                      | <b>800-992-6624 / 803-548-6633 - <a href="http://www.combi-intl.com">www.combi-intl.com</a></b> |                                                                                                                                                                                                                                                                                               |
| 21)                                          | BabyRide                          | 378099                                                                               | 05/01/16-08/31/19                                                                               | The 1-inch-wide front webbing strap used to adjust the harness does not meet FMVSS 213 breaking strength requirements and in certain circumstances, may not adequately restrain a child during a crash. Contact mfg. for more information.                                                    |
| 22)                                          | Coccoro                           | 8220x                                                                                | 01/01/09-06/29/16                                                                               | Too much force can be placed on the child when the car seat is installed forward-facing with only the vehicle's lap belt. All other installation methods are not affected. Contact mfg. for a cover to add to the bottom of the seat.                                                         |
| <b>Cybex (Columbus Trading-Partners USA)</b> |                                   |                                                                                      | <b>877-242-5676 <a href="http://cybex-online.com/en-us">cybex-online.com/en-us</a></b>          |                                                                                                                                                                                                                                                                                               |
| 23)                                          | Aton                              | 514xxxxxx                                                                            | 06/06/17-11/01/20                                                                               | The webbing for the front harness adjustment strap, used to snugly adjust the shoulder harness straps onto the infant, may fray, which can reduce its strength. Contact the manufacturer for replacement parts and installation instructions.                                                 |
| 24)                                          | Aton 2,<br>Aton 2<br>SensorSafe   | 515xxxxxx, 519xxxxxx,<br>521xxxxxx                                                   | 06/06/17-11/01/20                                                                               | The webbing for the front harness adjustment strap, used to snugly adjust the shoulder harness straps onto the infant, may fray, which can reduce its strength. Contact the manufacturer for replacement parts and installation instructions.                                                 |
| 25)                                          | Aton G                            | 522001441, 522001443,<br>522001445, 522001447,<br>522004777, 522004779               | 02/20/23-05/10/24                                                                               | The harness is attached to the underside of the car seat via metal harness anchor pins held in place by plastic hooks. The plastic hooks may bend causing the harness to detach. A detached harness will not properly restrain a child. Contact manufacturer for remedy kit and instructions. |
| 26)                                          | Aton G Swivel                     | 522004167, 522004169,<br>522004171, 522004173,<br>522005099, 522004781,<br>522004783 | 02/20/23-05/10/24                                                                               | The harness is attached to the underside of the car seat via metal harness anchor pins held in place by plastic hooks. The plastic hooks may bend causing the harness to detach. A detached harness will not properly restrain a child. Contact manufacturer for remedy kit and instructions. |
| 27)                                          | Aton M,<br>Aton M<br>SensorSafe   | 518xxxxx, 519xxxxxx                                                                  | 06/06/17-11/01/20                                                                               | The webbing for the front harness adjustment strap, used to snugly adjust the shoulder harness straps onto the infant, may fray, which can reduce its strength. Contact the manufacturer for replacement parts and installation instructions.                                                 |
| 28)                                          | Aton Q                            | 515xxxxxx, 517xxxxxx                                                                 | 06/06/17-11/01/20                                                                               | The webbing for the front harness adjustment strap, used to snugly adjust the shoulder harness straps onto the infant, may fray, which can reduce its strength. Contact the manufacturer for replacement parts and installation instructions.                                                 |
| 29)                                          | Cloud Q,<br>Cloud Q<br>SensorSafe | 515xxxxxx, 517xxxxxx,<br>519xxxxxx, 521xxxxxx                                        | 06/06/17-11/01/20                                                                               | The webbing for the front harness adjustment strap, used to snugly adjust the shoulder harness straps onto the infant, may fray, which can reduce its strength. Contact the manufacturer for replacement parts and installation instructions.                                                 |

| List No.                                                                    | Model Name                          | Model No. (X or # = more numbers or letters follow)                         | Mfg Date          | Problem Type and Consumer Action                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
|-----------------------------------------------------------------------------|-------------------------------------|-----------------------------------------------------------------------------|-------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Cybex (CTP) (continued)</b>                                              |                                     |                                                                             |                   |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| 30)                                                                         | Eos and Aton G Travel System        | 522003793, 522003795, 522003797, 522003799, 522003897                       | 02/20/23-05/10/24 | The harness is attached to the underside of the car seat via metal harness anchor pins held in place by plastic hooks. The plastic hooks may bend causing the harness to detach. A detached harness will not properly restrain a child. Contact manufacturer for remedy kit and instructions.                                                                                                                                                                                                                                                                                                                                                                                       |
| >> 31)                                                                      | Eos and Aton G Swivel Travel System | 522004805, 522005355                                                        | 02/20/23-05/10/24 | The harness is attached to the underside of the car seat via metal harness anchor pins held in place by plastic hooks. The plastic hooks may bend causing the harness to detach. A detached harness will not properly restrain a child. Contact manufacturer for remedy kit and instructions.                                                                                                                                                                                                                                                                                                                                                                                       |
| 32)                                                                         | Sirona M                            | 518000385, 518000387, 518002145, 518002149, 518002151, 518002153, 519000211 | 11/03/17-08/31/18 | It is possible for a child to access and pick pieces of foam from the child seat headrest pad. Loose pieces of foam can be a choking hazard. Contact manufacturer for a remedy kit.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |
| <b>Diono 855-463-4666 - www.us.diono.com</b>                                |                                     |                                                                             |                   |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| 33)                                                                         | Cambria 2                           | 31200-US-01, 31201-US-01, 31202-US-01                                       | 09/05/20-11/30/20 | When used as a highback booster, a crack between the headrest and backrest can occur in a crash, allowing the headrest to separate. Affected products have serial numbers that start with 648762, 648801, 648802, 648803, 648825, 648842, 648843, 648844, 648846, 648847, 648925, or 648926. Contact mfg. for a replacement backrest/headrest.                                                                                                                                                                                                                                                                                                                                      |
| 34)                                                                         | Olympia                             | 30100                                                                       | 04/12/14-03/31/15 | <p>The seat may not adequately protect a child in a crash when used in harnessed mode and installed forward-facing.</p> <p><b>Children who weigh more than 65 lbs:</b> Seats installed forward-facing (with any installation method) require the use of a top tether for children weighing more than 65 lbs in harnessed mode. If no top tether anchor is available, use the seat in booster mode.</p> <p><b>Children who weigh 65 lbs or less:</b> Seats installed forward-facing using only the lap belt require the use of the top tether for children who weigh 65 lbs or less in harnessed mode. If no top tether anchor is available, contact mfg. for a free repair kit.</p> |
| 35)                                                                         | Pacifica                            | 30400, 300000                                                               | 04/12/14-05/13/16 |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| 36)                                                                         | Radian R100                         | 16600, 16000                                                                | 01/03/14-09/05/17 |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| 37)                                                                         | Radian R120                         | 16800, 16000                                                                | 01/03/14-08/30/17 |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| 38)                                                                         | Radian RXT                          | 16900, 16000                                                                | 11/25/13-09/05/17 |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| 39)                                                                         | Rainier                             | 30300, 300000                                                               | 04/12/14-09/05/17 |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| <b>Disney Baby (Dorel) 877-657-9546 / www.djgusa.com</b>                    |                                     |                                                                             |                   |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| >> 40)                                                                      | MagicSquad 3-in-1                   | BC167GNT, BC167GNU                                                          | 02/28/23-03/07/25 | The forward-facing installation label has incorrect height information for using the internal harness. The correct height is stated in the car seat manual (34-49 in / 87-125 cm). The car seat can continue to be used as instructed by the car seat manual. Contact manufacturer for a replacement label.                                                                                                                                                                                                                                                                                                                                                                         |
| <b>Evenflo 800-525-2472 / 800-233-5921 / 800-490-7497 - www.evenflo.com</b> |                                     |                                                                             |                   |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                     |
| >> 41)                                                                      | Amp                                 | 34011243C                                                                   | 01/01/18-12/31/24 | Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.                                                                                                                                                                                                                                                                                                                                                                                                                                        |
| >> 42)                                                                      | Big Kid LX                          | 31912381C                                                                   | 01/01/18-12/31/24 | Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.                                                                                                                                                                                                                                                                                                                                                                                                                                        |

| <b>List No.</b>            | <b>Model Name</b>                             | <b>Model No. (X or # = more numbers or letters follow)</b>      | <b>Mfg Date</b>                                                                | <b>Problem Type and Consumer Action</b>                                                                                                                                                                                                                                                                                                              |
|----------------------------|-----------------------------------------------|-----------------------------------------------------------------|--------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Evenflo (continued)</b> |                                               |                                                                 |                                                                                |                                                                                                                                                                                                                                                                                                                                                      |
| >> 43)                     | Everyfit All4One, Everykid                    | CS300212376C, CS300212408C, CS300212340C                        | 01/01/18-12/31/24                                                              | Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.                                                                                                         |
| >> 44)                     | Everystage DLX                                | 39212241C                                                       | 01/01/18-12/31/24                                                              | Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.                                                                                                         |
| 45)                        | Evolve 3-in-1                                 | 34411700, 34411741                                              | 02/26/15-02/09/16                                                              | The central front harness adjuster button may be within the child's reach which could allow the child to loosen the harness and be at an increased risk of injury in the event of a crash. Contact mfg. for a free repair kit.                                                                                                                       |
| >> 46)                     | Gold Revolve360                               | 38412311C                                                       | 01/01/18-12/31/24                                                              | Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.                                                                                                         |
| >> 47)                     | Go Time Sport Booster                         | 35012433C                                                       | 01/01/18-12/31/24                                                              | Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.                                                                                                         |
| >> 48)                     | LiteMax (incl. those sold with travel system) | 6391600C, 53212311C, 56211976C, 57312205C, 53112311C, 53312418C | 01/01/18-12/31/24                                                              | Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.                                                                                                         |
| >> 49)                     | Maestro Sport                                 | 34912200C, 34912258C                                            | 01/01/18-12/31/24                                                              | Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.                                                                                                         |
| >> 50)                     | Safemax (incl. those sold with travel system) | 56012477C, 57112454C                                            | 01/01/18-12/31/24                                                              | Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.                                                                                                         |
| >> 51)                     | Sonus                                         | 34712059C                                                       | 01/01/18-12/31/24                                                              | Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.                                                                                                         |
| >> 52)                     | Spectrum                                      | 34212036C                                                       | 01/01/18-12/31/24                                                              | Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.                                                                                                         |
| >> 53)                     | Symphony Elite, Symphony Sport, Symphony DLX  | 34611709C, 34512335C, 34612173C, 34631038C                      | 01/01/18-12/31/24                                                              | Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.                                                                                                         |
| >> 54)                     | Tribute                                       | 3811198C                                                        | 01/01/18-12/31/24                                                              | Seats meet US safety standards but lack required US registration card. Continue to use seat in accordance with manufacturer instructions. Contact manufacturer for replacement registration card or register online at manufacturer website.                                                                                                         |
| <b>Graco</b>               |                                               |                                                                 | <b>800-345-4109 - <a href="http://www.gracobaby.com">www.gracobaby.com</a></b> |                                                                                                                                                                                                                                                                                                                                                      |
| 55)                        | Extend2Fit                                    | 1954477                                                         | 11/27/15-01/20/16                                                              | The recline labels on affected models do not meet FMVSS 213. Labels on the side of affected car seats, including the recline label, may not be in the same language (i.e. all English on one side of the car seat and all Spanish on the other side). Recall does not affect the safety performance of the seat. Contact mfg for replacement labels. |
| 56)                        | Milestone                                     | 1910130, 1923980, 1926538, 1926539                              | 07/09/15-10/09/15                                                              | The labels on affected seats do not include specific phrasing about how to install the car seat, as required by FMVSS 213. Recall does not affect the safety performance of the seat. Contact mfg. for free replacement labels.                                                                                                                      |

| List No.                     | Model Name                      | Model No. (X or # = more numbers or letters follow)        | Mfg Date                                      | Problem Type and Consumer Action                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |
|------------------------------|---------------------------------|------------------------------------------------------------|-----------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <b>Graco (continued)</b>     |                                 |                                                            |                                               |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
| 57)                          | TurboBooster                    | 1963973, 1963974,<br>1963975, 1963976,<br>1967886, 1975173 | 12/22/15-<br>04/05/16                         | Instructions are missing the information required by FMVSS 213 that the seats should be securely belted to the vehicle at all times, even if the seat is unoccupied. Recall does not affect the safety performance of the seat. Contact mfg. to obtain missing instructions.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                       |
| <b>Harmony</b>               |                                 |                                                            | <b>877-306-1001 / www.harmonyjuvenile.com</b> |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
| 58)                          | Big Boost Deluxe                | All Models                                                 | 11/01/15-<br>06/24/17                         | In the event of a crash, a child's chest may experience forces that exceed FMVSS 213 limits. Owners should contact Harmony customer service for more information.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
| <b>JD E-Commerce America</b> |                                 |                                                            | <b>302-426-4543 / overseas-service@jd.com</b> |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
| 59)                          | Marainbow                       | Any Model                                                  | Any Date                                      | This seat (as well as materially similar products – see portable infant/child seat) does not meet FMVSS 213 requirements for installation and labeling and may increase the risk of injury. Contact manufacturer for a refund and do not use seat.<br><br>A list of specific seats included in this recall:<br><a href="https://static.nhtsa.gov/odi/rci/2022/RMISC-22C008-4093.pdf">https://static.nhtsa.gov/odi/rci/2022/RMISC-22C008-4093.pdf</a>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
| 60)                          | <b>Joybuy Express</b>           | <b>See JD E-Commerce America</b>                           |                                               |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
| <b>Maxi-Cosi (Dorel)</b>     |                                 |                                                            | <b>877-657-9546 / www.djgusa.com</b>          |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
| 61)                          | Coral XP                        | IC313xxx                                                   | 05/01/20-<br>02/28/23                         | <b>Recall issue #1)</b> The lower anchors used to secure the car seat base may fail, allowing the seat to detach, which could increase the risk of injury. Discontinue use of lower anchors immediately and install using vehicle seat belt. Contact manufacturer for a replacement base. Note: The stroller included as part of the travel system has not been recalled, only the car seat component. Check model # on the car seat.<br><br><b>Recall issue #2)</b> The inner carrier of the child restraint is not sufficient to restrain a child without the use of the outer carrier. Only use the inner carrier when attached to the outer carrier and installed with the vehicle seat belt (see above recall), consistent with the existing instruction booklet and labels. Contact manufacturer for refund or replacement seat. Note: The stroller included as part of the travel system has not been recalled, only the car seat component. Check model # on the car seat. |
|                              | <i>Coral XP Travel Systems:</i> |                                                            |                                               |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
|                              | Mara XT                         | TR434xxx                                                   |                                               |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
|                              | Tayla XP                        | TR433xxx                                                   |                                               |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
| 62)                          | Infant Car Seat Base            | IC335xxx                                                   | 05/01/20-<br>02/28/23                         | The lower anchors used to secure the car seat base may fail, allowing the seat to detach, which could increase the risk of injury. Discontinue use of lower anchors immediately and install using vehicle seat belt. Contact manufacturer for a replacement base.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
| 63)                          | Mico XP Max Infant Car Seat     | IC336xxx, IC337xxx,<br>IC338xxx                            | 05/01/20-<br>02/28/23                         | The lower anchors used to secure the car seat base may fail, allowing the seat to detach, which could increase the risk of injury. Discontinue use of lower anchors immediately and install using vehicle seat belt. Contact manufacturer for a replacement base.<br><br>Note: The stroller included as part of the travel system has not been recalled, only the car seat component. Check model # on the car seat.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
|                              | <i>Mico XP Travel Systems:</i>  |                                                            |                                               |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
|                              | Adorra                          | TR430xxx                                                   |                                               |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
|                              | Gia XP                          | TR416xxx                                                   |                                               |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
|                              | Tayla                           | TR428xxx                                                   |                                               |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
|                              | Zelia 2 Max                     | TR427xxx                                                   |                                               |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
| 64)                          | Mico Luxe + Infant Car Seat     | IC370xxx                                                   | 05/01/20-<br>02/28/23                         | The lower anchors used to secure the car seat base may fail, allowing the seat to detach, which could increase the risk of injury. Discontinue use of lower anchors immediately and install using vehicle seat belt. Contact manufacturer for a replacement base.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |

| List No.                                                                                                                                                                                                                                            | Model Name                                                                                                                                                                                                                                                                           | Model No. (X or # = more numbers or letters follow)                                                                                                          | Mfg Date            | Problem Type and Consumer Action                                                                                                                                                                                                                                                                                                                                     |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 65)                                                                                                                                                                                                                                                 | Pria 70                                                                                                                                                                                                                                                                              | CC133xxx                                                                                                                                                     | 01/01/19 - 07/31/19 | When installed forward-facing using only the vehicle lap belt, the seat may not adequately protect the child from head injury in the event of a crash. As such, these child seats fail to conform to the requirements of FMVSS 213. Contact manufacturer for more information and a free remedy kit.                                                                 |
| 66)                                                                                                                                                                                                                                                 | Pria 85<br>Pria 85 Max                                                                                                                                                                                                                                                               | CC121xxx, CC156xxx, CC182xxx, CC183xxx, CC191xxx, CC201xxx, CC212xxx, CC213xxx, CC217xxx, CC221xxx                                                           | 01/01/19- 08/17/21  | When installed forward-facing using only the vehicle lap belt, the seat may not adequately protect the child from head injury in the event of a crash. As such, these child seats fail to conform to the requirements of FMVSS 213. Contact manufacturer for more information and a free remedy kit.                                                                 |
| <b>Nuna</b>                                                                                                                                                                                                                                         |                                                                                                                                                                                                                                                                                      | <b>855-686-2891 - <a href="http://www.nunababy.com">www.nunababy.com</a></b>                                                                                 |                     |                                                                                                                                                                                                                                                                                                                                                                      |
| 67)                                                                                                                                                                                                                                                 | Rava                                                                                                                                                                                                                                                                                 | All Models                                                                                                                                                   | 07/16/16- 10/25/23  | Debris may enter the front harness adjuster and cause the teeth of the adjuster mechanism to no longer properly clamp onto the adjuster strap. This can result in the harness not remaining tight. If the harness is functioning properly, the car seat can continue to be used in accordance with manufacturer instructions. Contact manufacturer for a remedy kit. |
| <b>Portable Child/Infant Seat</b>                                                                                                                                                                                                                   |                                                                                                                                                                                                                                                                                      | <b>Contact NHTSA 888-327-4236 / <a href="https://www.nhtsa.gov/report-a-safety-problem">https://www.nhtsa.gov/report-a-safety-problem</a> with concerns.</b> |                     |                                                                                                                                                                                                                                                                                                                                                                      |
| 68)                                                                                                                                                                                                                                                 | <b>Consumer Advisory</b> – A number of products sold as "portable child/infant seats" fail to meet FMVSS213 requirements for protection, installation, and/or labeling and may increase the risk of injury. These seats are not certified for the protection of children in the U.S. |                                                                                                                                                              |                     |                                                                                                                                                                                                                                                                                                                                                                      |
| Signs of seats that fail to meet FMVSS213: no lower anchor attachments, labels in languages other than English and Spanish (or missing entirely), no manufacturer contact information, and/or missing instruction labels with pictures or diagrams. |                                                                                                                                                                                                                                                                                      |                                                                                                                                                              |                     |                                                                                                                                                                                                                                                                                                                                                                      |
| <b>Safety 1st (Dorel)</b>                                                                                                                                                                                                                           |                                                                                                                                                                                                                                                                                      | <b>877-657-9546 / <a href="http://www.djgusa.com">www.djgusa.com</a></b>                                                                                     |                     |                                                                                                                                                                                                                                                                                                                                                                      |
| >> 69)                                                                                                                                                                                                                                              | Boost & Go, Boost & Go Essential                                                                                                                                                                                                                                                     | BC163HAS, BC163HAY, BC181HFW, BC181HFWD, BC181HGW                                                                                                            | 02/28/23- 03/07/25  | The forward-facing installation label has incorrect height information for using the internal harness. The correct height is stated in the car seat manual (34-49 in / 87-125 cm). The car seat can continue to be used as instructed by the car seat manual. Contact manufacturer for a replacement label.                                                          |
| >> 70)                                                                                                                                                                                                                                              | Comfort Ride 3 in 1                                                                                                                                                                                                                                                                  | BC159GKO, BC159HAA, BC159HBE, BC159HBED, BC159HBH                                                                                                            | 02/28/23- 03/07/25  | The forward-facing installation label has incorrect height information for using the internal harness. The correct height is stated in the car seat manual (34-49 in / 87-125 cm). The car seat can continue to be used as instructed by the car seat manual. Contact manufacturer for a replacement label.                                                          |
| 71)                                                                                                                                                                                                                                                 | Onboard35 SecureTech / SecureTech Base                                                                                                                                                                                                                                               | IC351xxx<br>IC372xxx                                                                                                                                         | 05/01/20- 02/28/23  | The lower anchors used to secure the car seat base may fail, allowing the seat to detach, which could increase the risk of injury. Discontinue use of lower anchors immediately and install using vehicle seat belt. Contact manufacturer for a replacement base.                                                                                                    |
| 72)                                                                                                                                                                                                                                                 | <b>Snugli</b>                                                                                                                                                                                                                                                                        | See Evenflo                                                                                                                                                  |                     |                                                                                                                                                                                                                                                                                                                                                                      |
| <b>WAYB</b>                                                                                                                                                                                                                                         |                                                                                                                                                                                                                                                                                      | <b>888-924-9292 - <a href="http://www.wayb.com">www.wayb.com</a></b>                                                                                         |                     |                                                                                                                                                                                                                                                                                                                                                                      |
| 73)                                                                                                                                                                                                                                                 | Pico                                                                                                                                                                                                                                                                                 | All Models<br>CSTPI-##-001                                                                                                                                   | 03/01/19- 05/12/19  | The headrest's aluminum tubular frame can break allowing the headrest to detach. Contact mfg. for replacement headrest and instructions.                                                                                                                                                                                                                             |



For the model numbers "x" = more numbers or letters follow

Index number refers to "List No." for each listing

## Index of Recalls and Safety Notifications

For the model numbers, "x" or "#" means that more numbers or letters follow.

Model numbers and model names for car seats under recall are followed by their index number which corresponds to the "List No." for each listing. If the model number is not found, check the model name also. Model numbers are not available for all model names.

|                                            |    |                                          |        |                             |            |
|--------------------------------------------|----|------------------------------------------|--------|-----------------------------|------------|
| <b>4moms</b>                               |    | # EXLT34A . . . . .                      | 9      | Liingo . . . . .            | 17, 18     |
| # 1032 . . . . .                           | 1  | # S01298600 . . . . .                    | 8      | Olli . . . . .              | 19         |
| Infant Car Seat . . . . .                  | 1  | # S02063xxx . . . . .                    | 7, 8   | Ozzi . . . . .              | 20         |
|                                            |    | # S02064000 . . . . .                    | 8      |                             |            |
| <b>Angel Guard (Merritt Manufacturing)</b> |    | # S03803xxx . . . . .                    | 7      | <b>Combi</b>                |            |
| AngelRide Car Bed . . . . .                | 2  | # S04144xxx . . . . .                    | 7      | # 378099 . . . . .          | 21         |
|                                            |    | # S04145000 . . . . .                    | 7      | # 8220x . . . . .           | 22         |
| <b>babidéal (Dorel China America)</b>      |    | # S04281xxx . . . . .                    | 8      | BabyRide . . . . .          | 21         |
| # BC901BPXL . . . . .                      | 3  | # S04402800 . . . . .                    | 7      | Coccoro . . . . .           | 22         |
| Storm Booster . . . . .                    | 3  | # S04628500 . . . . .                    | 8      |                             |            |
|                                            |    | # S04884xxx . . . . .                    | 7      |                             |            |
| <b>Baby Jogger</b>                         |    | # S04975600 . . . . .                    | 7      | <b>Cybex (CTP)</b>          |            |
| # BJ64510 . . . . .                        | 4  | # S04978900 . . . . .                    | 7      | # 514xxxxxx . . . . .       | 23         |
| # BJ64529 . . . . .                        | 4  | # S05260200 . . . . .                    | 7      | # 515xxxxxx . . . . .       | 24, 28, 29 |
| City GO Car Seat . . . . .                 | 4  | # S06018800 . . . . .                    | 8      | # 517xxxxxx . . . . .       | 28, 29     |
|                                            |    | # S06020xxx . . . . .                    | 7, 8   | # 518000385 . . . . .       | 32         |
| <b>Baby Trend</b>                          |    | # S06051300 . . . . .                    | 8      | # 518000387 . . . . .       | 32         |
| # FB48417 . . . . .                        | 5  | # S06147100 . . . . .                    | 7      | # 518002145 . . . . .       | 32         |
| # FB49E14A . . . . .                       | 6  | # S921800 . . . . .                      | 7      | # 518002149 . . . . .       | 32         |
| # FB58181 . . . . .                        | 5  | # S923700 . . . . .                      | 8      | # 518002151 . . . . .       | 32         |
| Hybrid 3-in-1 Combo Booster Seat . . . . . | 6  | B-Safe 35 . . . . .                      | 7      | # 518002153 . . . . .       | 32         |
| Hybrid 3-in-1 LX . . . . .                 | 5  | B-Safe 35 Elite . . . . .                | 8      | # 518xxxxxx . . . . .       | 27         |
|                                            |    | B-Safe 35 Elite Travel Systems . . . . . | 8      | # 519000211 . . . . .       | 32         |
| <b>Britax</b>                              |    | B-Safe 35 Travel Systems . . . . .       | 7      | # 519xxxxxx . . . . .       | 24, 27, 29 |
| # E1A183F . . . . .                        | 7  | B-Safe BOB 35 . . . . .                  | 9      | # 521xxxxxx . . . . .       | 24, 29     |
| # E1A185x . . . . .                        | 7  | Companion . . . . .                      | 10     | # 522001441 . . . . .       | 25         |
| # E1A186R . . . . .                        | 7  | One4Life Slim ClickTight . . . . .       | 11     | # 522001443 . . . . .       | 25         |
| # E1A203F . . . . .                        | 7  |                                          |        | # 522001445 . . . . .       | 25         |
| # E1A205x . . . . .                        | 7  | <b>Chicco</b>                            |        | # 522001447 . . . . .       | 25         |
| # E1A206x . . . . .                        | 7  | # 04079561190070 . . . . .               | 12     | # 522003793 . . . . .       | 30         |
| # E1A207E . . . . .                        | 7  | # 07079561970070 . . . . .               | 12     | # 522003795 . . . . .       | 30         |
| # E1A215x . . . . .                        | 8  | MyFit Zip Air . . . . .                  | 12     | # 522003797 . . . . .       | 30         |
| # E1A216P . . . . .                        | 8  |                                          |        | # 522003799 . . . . .       | 30         |
| # E1A221Q . . . . .                        | 8  | <b>Clek</b>                              |        | # 522003897 . . . . .       | 30         |
| # E1A225x . . . . .                        | 8  | # F012 . . . . .                         | 14     | # 522004167 . . . . .       | 26         |
| # E1A226L . . . . .                        | 8  | # F014 . . . . .                         | 14     | # 522004169 . . . . .       | 26         |
| # E1D197A . . . . .                        | 11 | # F015 . . . . .                         | 14     | # 522004171 . . . . .       | 26         |
| # E1D197B . . . . .                        | 11 | # F016 . . . . .                         | 14     | # 522004173 . . . . .       | 26         |
| # E1D197F . . . . .                        | 11 | # F017 . . . . .                         | 14     | # 522004777 . . . . .       | 25         |
| # E1D197G . . . . .                        | 11 | # F018 . . . . .                         | 14     | # 522004779 . . . . .       | 25         |
| # E9L14 . . . . .                          | 10 | # F019 . . . . .                         | 14     | # 522004781 . . . . .       | 26         |
| # E9L20 . . . . .                          | 10 | # FL15 . . . . .                         | 13     | # 522004783 . . . . .       | 26         |
| # E9L80 . . . . .                          | 10 | # FL16 . . . . .                         | 13     | # 522004805 . . . . .       | 31         |
| # E9LS5xx . . . . .                        | 8  | # FL17 . . . . .                         | 13     | # 522005099 . . . . .       | 26         |
| # E9LT34x . . . . .                        | 9  | # FL18 . . . . .                         | 13     | # 522005355 . . . . .       | 31         |
| # E9LT35X . . . . .                        | 9  | # FL19 . . . . .                         | 13     | Aton . . . . .              | 23         |
| # E9LU65V . . . . .                        | 7  | # LG19U1 . . . . .                       | 15, 16 | Aton 2 . . . . .            | 24         |
| # E9LU66x . . . . .                        | 7  | # LGO20U1 . . . . .                      | 17, 18 | Aton 2 SensorSafe . . . . . | 24         |
| # E9LU67x . . . . .                        | 7  | Flo . . . . .                            | 13     | Aton G . . . . .            | 25         |
| # EXA185M . . . . .                        | 7  | Foonf . . . . .                          | 14     | Aton G Swivel . . . . .     | 26         |
| # EXA216L . . . . .                        | 8  | Liing . . . . .                          | 15, 16 | Aton M . . . . .            | 27         |
|                                            |    |                                          |        | Aton M SensorSafe . . . . . | 27         |

For the model numbers "x" = more numbers or letters follow

Index number refers to "List No." for each listing

**Cybox (continued)**

|                                     |    |
|-------------------------------------|----|
| Aton Q                              | 28 |
| Cloud Q                             | 29 |
| Cloud Q SensorSafe                  | 29 |
| Eos and Aton G Swivel Travel System | 31 |
| Eos and Aton G Travel System        | 30 |
| Sirona M                            | 32 |

**Diono**

|               |            |
|---------------|------------|
| # 16000       | 36, 37, 38 |
| # 16600       | 36         |
| # 16800       | 37         |
| # 16900       | 38         |
| # 300000      | 35, 39     |
| # 30100       | 34         |
| # 30300       | 39         |
| # 30400       | 35         |
| # 31200-US-01 | 33         |
| # 31201-US-01 | 33         |
| # 31202-US-01 | 33         |
| Cambria 2     | 33         |
| Olympia       | 34         |
| Pacifica      | 35         |
| Radian R100   | 36         |
| Radian R120   | 37         |
| Radian RXT    | 38         |
| Rainier       | 39         |

**Disney Baby (Dorel)**

|                   |    |
|-------------------|----|
| # BC167GNT        | 40 |
| # BC167GNU        | 40 |
| MagicSquad 3-in-1 | 40 |

**Dorel (Disney Baby)**

|                   |    |
|-------------------|----|
| # BC167GNT        | 40 |
| # BC167GNU        | 40 |
| MagicSquad 3-in-1 | 40 |

**Dorel (Maxi-Cosi)**

|            |    |
|------------|----|
| # CC121xxx | 66 |
| # CC133xxx | 65 |
| # CC156xxx | 66 |
| # CC182xxx | 66 |
| # CC183xxx | 66 |
| # CC191xxx | 66 |
| # CC201xxx | 66 |
| # CC212xxx | 66 |
| # CC213xxx | 66 |
| # CC217xxx | 66 |
| # CC221xxx | 66 |
| # IC313xxx | 61 |
| # IC335xxx | 62 |
| # IC336xxx | 63 |
| # IC337xxx | 63 |
| # IC338xxx | 63 |
| # IC370xxx | 64 |
| # TR416xxx | 63 |
| # TR427xxx | 63 |
| # TR428xxx | 63 |

|             |    |
|-------------|----|
| # TR430xxx  | 63 |
| # TR433xxx  | 61 |
| # TR434xxx  | 61 |
| Adorra      | 63 |
| Coral XP    | 61 |
| Gia XP      | 63 |
| IC335xxx    | 62 |
| Mara XT     | 61 |
| Mico Luxe + | 64 |
| Mico XP Max | 63 |
| Pria 70     | 65 |
| Pria 85     | 66 |
| Pria 85 Max | 66 |
| Tayla       | 63 |
| Tayla XT    | 61 |
| Zelia 2 Max | 63 |

**Dorel (Safety 1st)**

|                      |    |
|----------------------|----|
| # BC159GKO           | 70 |
| # BC159HAA           | 70 |
| # BC159HBE           | 70 |
| # BC159HBED          | 70 |
| # BC159HBH           | 70 |
| # BC163HAS           | 69 |
| # BC163HAY           | 69 |
| # BC181HFW           | 69 |
| # BC181HFW           | 69 |
| # BC181HFW           | 69 |
| # BC181HFW           | 69 |
| # IC351xxx           | 71 |
| # IC372xxx           | 71 |
| Boost & Go           | 69 |
| Boost & Go Essential | 69 |
| Comfort Ride 3 in 1  | 70 |
| Onboard35 SecureTech | 71 |
| SecureTech Base      | 71 |

**Dorel China America (babidéal)**

|               |   |
|---------------|---|
| # BC901BPXL   | 3 |
| Storm Booster | 3 |

**Evenflo**

|             |    |
|-------------|----|
| # 31912381C | 42 |
| # 34011243C | 41 |
| # 34212036C | 52 |
| # 34411700  | 45 |
| # 34411741  | 45 |
| # 34512335C | 53 |
| # 34611709C | 53 |
| # 34612173C | 53 |
| # 34631038C | 53 |
| # 34712059C | 51 |
| # 34912200C | 49 |
| # 34912258C | 49 |
| # 35012433C | 47 |
| # 3811198C  | 54 |
| # 38412311C | 46 |
| # 39212241C | 44 |
| # 53112311C | 48 |
| # 53212311C | 48 |

|                       |    |
|-----------------------|----|
| # 53312418C           | 48 |
| # 56012477C           | 50 |
| # 56211976C           | 48 |
| # 57112454C           | 50 |
| # 57312205C           | 48 |
| # 6391600C            | 48 |
| # CS300212340C        | 43 |
| # CS300212376C        | 43 |
| # CS300212408C        | 43 |
| Amp                   | 41 |
| Big Kid LX            | 42 |
| Everyfit All4One      | 43 |
| Everykid              | 43 |
| Everystage DLX        | 44 |
| Evolve 3-in-1         | 45 |
| Go Time Sport Booster | 47 |
| Gold Revolve360       | 46 |
| LiteMax               | 48 |
| Maestro Sport         | 49 |
| Safemax               | 50 |
| Sonus                 | 51 |
| Spectrum              | 52 |
| Symphony DLX          | 53 |
| Symphony Elite        | 53 |
| Symphony Sport        | 53 |
| Tribute               | 54 |

**Graco**

|              |    |
|--------------|----|
| # 1910130    | 56 |
| # 1923980    | 56 |
| # 1926538    | 56 |
| # 1926539    | 56 |
| # 1954477    | 55 |
| # 1963973    | 57 |
| # 1963974    | 57 |
| # 1963975    | 57 |
| # 1963976    | 57 |
| # 1967886    | 57 |
| # 1975173    | 57 |
| Extend2Fit   | 55 |
| Milestone    | 56 |
| TurboBooster | 57 |

**Harmony**

|                     |    |
|---------------------|----|
| # 9999 - All Models | 58 |
| Big Boost Deluxe    | 58 |

**JD E-Commerce America**

|           |    |
|-----------|----|
| Marainbow | 59 |
|-----------|----|

**Joybuy Express**

|                           |    |
|---------------------------|----|
| See JD E-Commerce America | 60 |
|---------------------------|----|

**Maxi-Cosi (Dorel)**

|            |    |
|------------|----|
| # CC121xxx | 66 |
| # CC133xxx | 65 |
| # CC156xxx | 66 |
| # CC182xxx | 66 |
| # CC183xxx | 66 |

For the model numbers "x" = more numbers or letters follow

Index number refers to "List No." for each listing

**Maxi-Cosi (Dorel) (continued)**

|                      |    |
|----------------------|----|
| # CC191xxx           | 66 |
| # CC201xxx           | 66 |
| # CC212xxx           | 66 |
| # CC213xxx           | 66 |
| # CC217xxx           | 66 |
| # CC221xxx           | 66 |
| # IC313xxx           | 61 |
| # IC335xxx           | 62 |
| # IC336xxx           | 63 |
| # IC337xxx           | 63 |
| # IC338xxx           | 63 |
| # IC370xxx           | 64 |
| # TR416xxx           | 63 |
| # TR427xxx           | 63 |
| # TR428xxx           | 63 |
| # TR430xxx           | 63 |
| # TR433xxx           | 61 |
| # TR434xxx           | 61 |
| Adorra               | 63 |
| Coral XP             | 61 |
| Gia XP               | 63 |
| Infant Car Seat Base | 62 |
| Mara XT              | 61 |
| Mico Luxe +          | 64 |
| Mico XP Max          | 63 |
| Pria 70              | 65 |
| Pria 85              | 66 |
| Pria 85 Max          | 66 |
| Tayla                | 63 |
| Tayla XP             | 61 |
| Zelia 2 Max          | 63 |

**Merritt Manufacturing (Angel Guard)**

|                   |   |
|-------------------|---|
| AngelRide Car Bed | 2 |
|-------------------|---|

**Nuna**

|      |    |
|------|----|
| Rava | 67 |
|------|----|

**Portable Child/Infant Seat**

|                      |    |
|----------------------|----|
| Any Model / Any Date | 68 |
|----------------------|----|

**Safety 1st (Dorel)**

|                      |    |
|----------------------|----|
| # BC159GKO           | 70 |
| # BC159HAA           | 70 |
| # BC159HBE           | 70 |
| # BC159HBED          | 70 |
| # BC159HBH           | 70 |
| # BC163HAS           | 69 |
| # BC163HAY           | 69 |
| # BC181HFW           | 69 |
| # BC181HFWD          | 69 |
| # BC181HGW           | 69 |
| # IC351xxx           | 71 |
| # IC372xxx           | 71 |
| Boost & Go           | 69 |
| Boost & Go Essential | 69 |
| Comfort Ride 3 in 1  | 70 |
| Onboard35 SecureTech | 71 |

|                 |    |
|-----------------|----|
| SecureTech Base | 71 |
|-----------------|----|

**WAYB**

|                |    |
|----------------|----|
| # CSTPI-##-001 | 73 |
| Pico           | 73 |